

Abstract of the Invention

A method for joining components in TiAl with a braze includes heating the braze with a laser.